Electric Transmission Work Zone Identification Kit



Dominion Virginia Power - System Protection

- Relay protection, metering and data acquisition for Transmission - Distribution Substations (800) & Generation (30) facilities
- 120 System Protection Technicians 3 states
 80 "contract" electricians
- 40% of our technical work force < 3 years experience
 Nearly triple the number of "contract" electricians since 2008
- Our Human Performance tools and training is focused on eliminating the inadvertent outages caused by human error

July 2009 - studied disturbance database for outages caused by System Protection human errors

Four most common errors:

Control wiring errors

Misoperation of test blades

Test jumpering incorrect point


Accessing incorrect control panel/control switch/device

We designed tools to address these "most common" errors

"Formalization" of the tools into a kit was key to our improvement


Control Wiring Contractors

Human Error Events vs. Capital Man-hours, Experience Levels



Work Zone Kit aimed at eliminating inadvertent equipment operations from:

Wiring Errors Test Jumpering Incorrect Points Accessing Incorrect Panel/Device



Use the Work Zone Kit Tools

- Equipment or components that look similar
- Equipment or components manipulated multiple times
- On or near trip sensitive or risk important equipment



Work Zone Kit

Train on How and When to Use the Kit

Reinforce

Pre- Job Briefing
Supervisor provides assessment and coaching



What's Included in Dominion's Kit?



Work Zone Identification Kit Insert (front)



Front Panel Barriers
Using Magnets
To Secure



Rear Panel Barriers Using Velcro Straps To Secure



Use of High Visibility Clip Jumper



Use of Flame Retardant Plastic Sheeting as a Barrier



Use of Flagging Hangers "Testing in Progress" and "Do Not Operate"



Use of Flagging Hanger "Abnormal Condition"



Use of Terminal Point Barriers



Use of "STOP - Equipment Under Test" Magnet

Work Zone Identification Kit Insert (back)

WORK ZONE BARRICADE and FLAGGING

BARRICADE and **FLAG** similar looking equipment that should be avoided during construction or equipment checkouts.

BARRICADE and **COVER UP** any terminal points that may operate equipment if contacted inadvertently.

FLAGGING

GREEN - FLAGGING

To **Identify** the correct device to be operated.

RED - FLAGGING

To **Identify** a device that should be avoided.

YELLOW - FLAGGING


To **Identify** an abnormal condition.

REMOVE

Remove barricades and flagging once the job is complete or at the end of the work shift.

Do not leave barricade and flagging on in-service equipment (i.e. panel fronts, control switches) after work shift has ended.





Work Zone Identification Kit Banners

- Create physical barriers direct worker to correct equipment/components & away from high risk equipment
- Text reminds of our human performance tools & terminology





Work Zone Identification Hangers for Flagging

- Identifies correct device to operate
- Flags abnormal conditions



Work Zone Identification Signage

Out of service equipment under test

 Wire caps to provide an insulated cover up for wires and lugs during transitional periods such as construction jobs.

OWire caps are color coded:

 Red caps - new wiring to be terminated in the future.

oGreen caps - wiring being removed.

Yellow caps - temporary conditions.

OWire caps sized to provide a secure fit (sock like) for multiple sized wires and lugs.



Wire Caps Instead of Tape


Terminal Point Barriers


oTerminal point barriers to cover up trip sensitive points on wiring blocks & provide a visual indication of the "trip" point locations.

oCover any "trip" point that may result in an unwanted event if inadvertently touched or bridged.



Terminal Point Barriers







Without Terminal Point Barriers

With Terminal Point Barriers

Terminal Point Barriers



o Cover adjacent points when using test jumper



Plastic Sheeting as Barrier

 Flame retardant plastic builds a physical barrier preventing incidental contact with "live" electrical control components.

 Plastic held in place with nylon blanket clamps.



The Requirement, the Expectation

- Technicians & Electricians work together to identify task risks during pre- job briefing/task preview
- Once risks are identified, use work zone kit tools to build appropriate barriers and defenses to prevent unwanted equipment operation
- Reduce the errors that cause outages!

All we ask is...

You borrow it
You use it
You improve it
You share it